

MAGERY NALYSIS VISION

19226

STATUS OF THE LAO CAI-HANOI AND PING HSIANG-HANOI RAILROAD LINES

> CIA/PIR 65024

DATE

August 1965

25X1C

SECRET

NO FOREIGN DISSEM

CIA/PIR-65024

CIA IMAGERY ANALYSIS DIVISION

STATUS OF THE LAO CAI-HANOI AND PING HSLANG-HANOI RAILROAD LINES

25X1D

Hanoi and Iao Kay-Hanoi Railroads was reviewed. The purpose of the review was to discover any new rail construction and to study extent of bomb damage to the aforementioned rail lines.

Bombing attacks have succeded in interdicting the Lao Cai-Hanoi Railroad. The following table describes the interdicted points and efforts at repair.

-1-

SECRET

NO FOREIGN DISSEM

CIA IMAGERY ANALYSIS DIVISION-

LAO CAI-HANOI RAILROAD BOMB DAMAGE ASSESSMENT

25X1D

FIGURE

LOCATION	DESCRIPTION OF DAMAGE	NO.
25.0 Mi. NW of Yen Bai 2157N - 10437E	105 foot half-through truss and deck-girder bridge. Center span and one approach span destroyed, unserviceable. Rail line destroy-	3
20.5 Mi. NW of Yen Bai 2155N - 10439E	ed for 100 feet south of bridge. 100 foot half-through truss and deck-girder bridge destroyed	None
3.5 Mi. NW of Yen Bai 2144N - 10450E	80 foot half-through truss bridge. Severly damaged, unserviceable. Rail line destroyed for 100 feet north of bridge.	Ц.
1.0 Mi. NW of Yen Bai 2143N - 10453E	Approximately 50 feet of rail line destroyed	5·;
At Yen Bai 2142N - 10453E	Yen Bai Railyard severely damaged, unserviceable.	
16 Mi. SE of Yen Bai 2130N - 10503E	Rail line interdicted by bomb craters	7

^{*} Last seen on post strike photography. No late coverage available to assess efforts at repair.

-2-

25X1C

SECRET NO FOREIGN DISSEM

CIA/PIR-65024

CIA IMAGERY ANALYSIS DIVISION

Railroad cars and locomotives were observed both north and south of
Yen Bai. The locomotives were usually separated from the cars, camouflaged,
and parked in cuts. One moving train was observed on photography of
This train was located 12 miles southeast of Yen Bai and moving very
slowly northwestward.

A river to road and/or river to road to rail transloading point on the Hanoi-Lao-Cai Line (Figure 8) is located three miles north of Yen Bai at 21~44N-104~50E.

25X1D

covered approximately 90 percent of the Ping Hsiang-Hanoi Railroad. Construction activity was observed in several places along a 20 mile stretch of the rail line from Dong Dang (21 56N - 106 42E) south to 21 41N - 106 40E. This activity occurred along some of the sharper curves in rough terrain. Other construction activity includes a newly completed rail spur serviceing a military camp 19 miles south of Dong Dang at 21 39N - 107 35E. A possible storage area under construction is located adjacent to the rail line at 21 46N - 106 45E.

There was no evidence present which would lead one to believe that the North Vietnamese are engaged in a change-of-gage of the Dong Dang-Hanoi Rail Line. Construction work observed along the present rail line appeared to be associated with rail realignment. The old abandoned section of roadbed, which is the only evidence of their prior attempt to change gage, showed no evidence of renewed construction activity.

_ 3_

SECRET

NO FOREIGN DISSEM

SECRET

25X1C

NO FOREIGN DISSEM

CIA/PIR-65024

CIA IMAGERY ANALYSIS DIVISION

25X1D

REFERENCES

MAPS

USAF Pilotage Chart, Sheet P.C. 616 CG, 3rd Edition, June 1962. (UNCLASSIFIED) USAF Pilotage Chart, Sheet P.C. 616 B, 3rd Edition, Feb. 1962. (UNCLASSIFIED)

CIA Base Map 51330, April 1965.

CIA Base Map 51330, April 1907.

(UNCLASSIFIED)

US Air Target Chart, Series 200, Sheet O616-2014L, 2nd Edition, Jan. 1964.

(SECRET)

4

SECRET

NO FOREIGN DISSEM

SECRET

25X1C

NO FOREIGN DISSEM

CIA/PIR-65024

CIA IMAGERY ANALYSIS DIVISION

US Air Target Chart, Series 200, Sheet 0616-1514L, 2nd Edition, May 1964 (SECRET)

REQUIREMENT


CIA. C-RR5-82,859


CIA/IAD PROJECT

30193-6

SECRET

NO FOREIGN DISSEM





CIA/PIR-65024 SECRET 25X1C FIGURE 4 YEN BAI BRIDGE SEVERELY DAMACED UNSERVICEABLE 44N - 104 50E 25X1D SECRET 25X1C



21 30N-105 03E 25X1C SECRET 25X1D

